

IDWAL

Report commissioned by:

Example shipping company

Organisation:

Example shipping organisation



PRE-SALE
REPORT

EXAMPLE GENERAL CARGO

IMO Number: 12345678

INSPECTED AT PLOCE CROATIA
OCTOBER 2022



REPORT TERMS OF USE


This report is intended for the sole use of **Example Company** and is designed to offer a condition evaluation of the subject vessel, as found on the day of the survey and in the opinion of the surveyor concerned. The report is subject to any access restrictions as described herein, and subject always to the level of cooperation afforded to the surveyor during the inspection itself. All details are given in good faith, and without guarantee.

This report has been prepared and issued by Idwal Marine Services Ltd to its Customer, **Example Company** in accordance with, and subject to, the General Terms and Conditions of Idwal Marine Services Ltd, a copy of which can be obtained at www.idwalmarine.com/terms-conditions. Attention is particularly drawn to restrictions on reproduction and disclosure of, and limits on reliance on, this Report as more fully set out therein.

To access all documents related to this report, and verify the authenticity of its contents, please view the full version available here:

customer.idwalmarine.com/00-0000

Pre-sale report reference:	00/000
Report commissioned for:	Example Company
Organisation:	Example Ship Management
PDF generated for:	example@example.com
Time & date:	10:00 (UTC) on 01st October 2022



CONTENTS

INSPECTION SUMMARY	3
COMPARE YOUR IDWAL GRADE	5
KEY NOTABLE ITEMS	6
DECARBONISATION SUMMARY	7
GRADING DATA	8
DESIGN AND CONSTRUCTION	9
HULL	10
MOORING DECKS	11
WEATHER DECKS AND FITTINGS	12
BALLAST TANKS AND SYSTEMS	13
ACCOMMODATION	14
BRIDGE AND NAVIGATION EQUIPMENT	15
ENGINE ROOM AND MACHINERY	16
FIRE FIGHTING EQUIPMENT AND SYSTEMS	17
LIFESAVING APPLIANCES	18
SAFE WORKING ENVIRONMENT	19
POLLUTION CONTROL	20
ONBOARD MANAGEMENT	22
VESSEL CAPABILITIES AND CARGO SYSTEMS	23

ADDITIONAL DOCUMENTS



Vessel documents




Vessel photos



INSPECTION SUMMARY

81

IDWAL
GRADEPloce,
Croatia

19 Oct 2022

Status:
Discharging8.5 Hours
AboardMajority of
documents
provided

The Example vessel is an Example DWT, Example Gross Tonnage, Portugal (Mar) flagged, geared General Cargo vessel built to a good standard by Example Shipbuilding, in Japan under Example class supervision and was delivered on the 8th November 2011. The vessel remains Classed with Example Class Society.

A Pre-Sale Inspection of the vessel was conducted on the 01st October 2022 in Ploce by Idwal under instruction from Example Ship Management.

Good cooperation was provided by the ship's crew with access granted to the cargo holds and ballast tanks. The vessel was alongside, discharging at the time of inspection.

The vessel was found to be in good overall condition with an Idwal Grade above the average for vessels of a similar age, type and size but with a few notable items found during the inspection. These are reported specifically in the notable items section of this report.

VESSEL PARTICULARS

Ship Name Previous	Example Vessel
Name	Example Vessel
IMO Number	123456789
Port of Registry	Example Port
Ship Type	General Cargo
Flag	Example Flag
Classification Society	Example Class
Registered Owner	Example Owner
Technical Manager	Example Manager
Shipbuilder	Example Shipbuilder
Delivery Date	01/01/2011
Dead Weight	Example MT
Gross Tonnage	Example MT
Net Tonnage	Example MT
Length Overall	Example m
Breadth	Example m
Depth	Example m
Summer Draught	Example m
Lightweight	Example MT

The onboard management was found to be good with the Safety Management system found to be well implemented and the vessel generally found to provide a safe working environment. The Port State Control (PSC) history was found to be good with 21 deficiencies and 0 detentions in the 14 inspections conducted in the past three years.


The vessel has a Class approved EEXI Technical File, dated September 2022, stating an Attained EEXI of 6.29 which is below the Required EEXI of 7.69.

The vessel's latest Carbon Intensity Indicator (CII) score was reported to be 6.55, which places the vessel in Band B for this current Calendar year. If the vessel were to maintain this Attained CII score with no tangible reduction or increase, then the vessel will likely be in Band B by 2023 when the regulations come into force. This means that the vessel will not be required to create a carbon reduction plan and may receive certain incentives.

COMPARE YOUR IDWAL GRADE

This section of the report allows you to compare your ship's grade with similar ships.

Your Idwal Grade vs other General Cargo vessels



This graph shows the distribution of Idwal Grades against your ship's sector.

KEY

Your Idwal grade	Average Idwal grade
Grade range	
> 90	71 - 90
51 - 70	30 - 50

Your Idwal Grade vs other General Cargo vessels, age 10-15 years



This graph shows your ship's Idwal Grade compared against other ships inspected in the same sector, within a similar age range, and how it compares against the average Idwal Grade for the sector.

KEY

Your Idwal grade	Average Idwal grade
All sector ships	Age comparable ships

The ship's grade may appear different when compared with the average of the two graphs. This is as a result of the second graph comparing a smaller and more focused sample of ships.

For a more in-depth analysis of where your vessel compares amongst its peers, please contact your Idwal sales rep.

KEY NOTABLE ITEMS

	Description	Action / Timeline	Estimated Cost [USD]
—	An accumulation of ice was noted around the pipework in the meat provision room.	De-frost and rectify root cause of excess ice build-up.	<\$1000
—	The latest lube oil analysis reports showed 'Caution' warning noted from auxiliary engines 1 and 3 due to increased vanadium content, with it also noted that the last test was conducted in April 2022.	The oils should be refreshed and re-tested as soon as possible. Oils with only a 'caution' warning are suitable for continued use.	<\$1000
—	Localised areas of corrosion were noted to the main deck walkways and cross deck areas, as well as to pipework fittings and supports.	Remedial cosmetic maintenance to be carried out as soon as practical.	<\$1000
—	A leak was noted from the port forward cylinder for cargo hatch cover number 4.	To be further investigated and rectified as soon as practical.	<\$1000
✓	A US coastguard approved Ballast Water Treatment System (BWTS) is installed.	Positive.	\$0
✓	The vessel has completed an out of water bottom survey within 12 months from the date of inspection.	Positive.	\$0
✓	The vessel is fitted with an Environmentally Acceptable Lubricant (EAL) in the stern tube and is therefore Vessel General Permit (VGP) compliant in this regard.	Positive.	\$0

Please note, all costs are estimations only, based on industry averages, and may vary depending on locations and scopes of work. These costs are provided to assist the reader to consider the potential Capex or Opex impact of the related Notable Item and should not be used for budgeting purposes without further internal assessment of their accuracy.

DECARBONISATION SUMMARY

The vessel has a Class approved EEXI Technical File, dated September 2022, stating an Attained EEXI of 6.29 which is below the Required EEXI of 7.69. The vessel's latest Carbon Intensity Indicator (CII) score was reported to be 6.55, which places the vessel in Band B for this current Calendar year. If the vessel were to maintain this Attained CII score with no tangible reduction or increase, then the vessel will likely be in Band B by 2023 when the regulations come into force. This means that the vessel will not be required to create a carbon reduction plan and may receive certain incentives. For more information about technologies to reduce a vessel's EEXI, the creation of the EEXI technical file or operational measures to reduce a vessel's Attained CII, please contact your Idwal sales representative.

EEXI

Required EEXI

7.69

gCO₂/t.nm

Attained EEDI/EEXI

6.29

gCO₂/t.nm

This vessel meets the required EEDI/EEXI

CII

Last Recorded CII (2021)

6.55

gCO₂/t.nm

Last attained CII Band (2021)

B

If the vessel maintains its last recorded CII score we anticipate it will be in Band B by 2023

GRADING DATA



The Idwal Grade® is an industry recognised measure of asset integrity. Using proprietary algorithms, the Idwal Grade is programmatically calculated from over 500 individual data points, captured during a rigorous and standardised inspection process. Our data-driven methodology ensures that our reports are consistent, accurate and free from bias.

SUB GRADES

The methodology used to calculate the Idwal Grade® is also applied to the grading of the different vessel areas and categories. Two key areas are the overall vessel condition and vessel management:

Condition



Management



The following are grades representing individual areas of interest of the vessel:

Design and Construction



Hull



Mooring Decks



Weather Decks and Fittings



Ballast Tanks and Systems



Accommodation



Bridge and Navigation Equipment



Engine Room and Machinery



Fire Fighting Equipment and Systems



Lifesaving Appliances



Safe Working Environment



Pollution Control



Onboard Management



Vessel Capabilities and Cargo Systems



Forthcoming Regulatory Compliance



Crew Welfare



Crew Performance



Safety Management



Planned Maintenance System (PMS)



Classification and Certification



PSC Performance



DESIGN AND CONSTRUCTION

80

The construction and design was found to be good overall, with the vessel built to IACS standards and Rules in Japan by Example Shipbuilding with the keel laid in 2010. The vessel is a General Cargo, with 5 holds, driven by a fixed pitch, direct drive propeller. The Main Engine is a NOx Tier 1, MAN B&W and the vessel has 3 Auxiliary Engines, and no shaft generator. It is not on the Enhanced Survey Program or

Extended Dry Docking schedule but does hold a Class notation for In Water Surveys. 4 Cargo Lifting Appliances are fitted. The UTM report showed only minor steel diminution. Apart from the equipment required by international rules and regulations, the bridge is also fitted with differential GPS and the engine room and machinery are fitted with incinerator sludge burning system, UMS capabilities and 2-stroke engine mechanical lubricator.

HULL

80

The hull was seen to be in a good overall condition, with the hull able to be inspected from all round while alongside. The vessel was found to be free of both major and minor structural defects and had only minor localised spot corrosion, up to approximately 2%

of the surface area, mainly located to midships boot top area. Hull markings were well painted and legible with minor marine fouling observed. The vessel's last out of water bottom survey was carried out on 24-Dec-21, with the vessel's next out of water bottom survey due by 07-Nov-26.

NOTABLE ITEMS

Description

Estimated
Cost
[USD]



Issue: The vessel has completed an out of water bottom survey within 12 months from the date of inspection.

Corrective Action: Positive.

\$0

MOORING DECKS

80

The Mooring decks were seen to be in a good condition overall with the decks found to be free of structural defects and had only minor localised surface corrosion, up to approximately 2% of the mooring deck plating total surface area, mainly located to deck plating and around foundations of mooring equipment. Deck fittings were found to be in a good condition with fairleads and mooring rollers free to turn when tested. All Hydraulic windlasses and winches were reported to be fully operational and free from hydraulic leakage as observed. Mooring machinery was in good condition with the band

brake linings seen to have substantial thicknesses and clutching and gearing arrangements sufficiently greased. Anchor chains and mooring ropes were in a good overall condition. Mooring practices were seen to be good and snap-back zone warnings were seen to be posted at the entrances to mooring areas as per industry best practice. The Bosun's store was in a fair overall condition with it noted that the housekeeping could be improved upon. The bitter end release arrangements were seen to be clear and unobstructed and the emergency towing booklet seen to be available near to the Foc'sle.

WEATHER DECKS AND FITTINGS

70

The Weather Decks and Fittings were seen to be in fair to good condition overall, primarily due to the levels of corrosion noted. The decks were found to be free of structural defects and had only minor localised, surface and spot corrosion, up to approximately 5% of the main deck plating total surface area, mainly located to deck walkways and cross deck areas. Deck fittings were found to be in a fair condition with localised areas of corrosion noted

to pipework fittings and supports however, pipework and fittings were seen to be generally free of leakages. The accommodation ladders and gangways were in a fair overall condition with scattered areas of corrosion noted to the starboard side accommodation ladder. However, provisions lifting appliances were in a good overall condition as observed.

NOTABLE ITEMS

Description

Estimated
Cost
[USD]



Issue: Localised areas of corrosion were noted to the main deck walkways and cross deck areas, as well as to pipework fittings and supports.

Corrective Action: Remedial cosmetic maintenance to be carried out as soon as practical.

<\$1000



BALLAST TANKS AND SYSTEMS

80

Ballast tanks and systems were deemed to be in a good overall condition. The Fore peak, and Number 5 Port and Starboard were entered for inspection however no photographs of previous tank entries were provided for review. The inspected ballast tanks were found to be generally free of significant structural defects and had only minor localised, surface and spot corrosion, up to approximately 5% of the ballast tanks total surface area, mainly located to the bulkheads and edges of supports in the fore peak, as well as localised areas of

corrosion noted to the bulkhead adjacent to the cargo hold in tank 5 port. Ballast tank fittings such as ladders and pipework were seen to be in a good overall condition with Anodes seen to be depleted up to 15%. Tanks were seen to have a minimal amount of mud/sediment accumulation but were free of any signs of staining from sewage or marine fouling. Ballast control systems such as valves and gauges were reported to be fully operational and all ballast pumps were in good working order and in good visual condition.

ACCOMMODATION

80

The accommodation areas were seen to be in a good condition overall with floor and wall coverings found to be in good condition and upholstery and furniture found to be free from deterioration and defects. The levels of housekeeping and cleanliness was found to be good but with the levels of hygiene in sanitary facilities seen to be fair with it noted that the cleanliness could be improved in the common sanitary facilities for the crew. The hospital was seen to be well equipped and ready for use with drugs and controlled substances locked away. The associated drugs log was kept up to date. The accommodation was found to be outfitted to an average quality. The Air Handling Unit (AHU) was found to be maintaining a comfortable temperature and was seen to be in good condition with no defects. The galley equipment was deemed to be in a good overall condition with all equipment reportedly in good working order. The

galley was found to be in a clean condition with the galley hoods also found to be kept clean. The vessel's walk-in cold rooms were found to be clean and hygienic with temperatures at the required levels. Provision room components were seen to have isolated defects such as an accumulation of ice note around the pipework in the meat room. The external superstructure was found to be free of structural defects and was free of coating breakdown and corrosion. The external superstructure fittings were seen to be in a fair overall condition with localised areas of corrosion noted to the air condition room manhole cover located next to the CO2 room entrance, but with all external accommodation doors in good working order and properly closing. The Crew Welfare was found to be in fair to good overall with it noted that the vessel is fitted with a paid to access and limited use Wi-Fi system though crew were reported to have access to a well-stocked bond store.

NOTABLE ITEMS

Description

Estimated Cost [USD]



Issue: An accumulation of ice was noted around the pipework in the meat provision room.

Corrective Action: De-frost and rectify root cause of excess ice build-up.

<\$1000



BRIDGE AND NAVIGATION EQUIPMENT

80

The Bridge and navigation equipment were found to be in a good condition overall with housekeeping found to be good and with all bridge equipment reported to be fully operational. The vessel's VDR was found to be free from any unanticipated alarms with collection instructions posted nearby and with the Bridge Navigation Watch Alarm System (BNWAS) reported to be fully operational. The vessel's primary means of navigation, as listed on form E of the safety equipment certificate is a dual ECDIS system which were found to be up to date. RADAR blind sectors were seen to be posted near the RADARs with the compass deviation card up-to-date and available near to the helm. The compass deviation log was found to be satisfactory, with no major deviations and generally up-to-date. The vessel is licensed to cover GMDSS sea areas A1, A2, and A3 and had a valid shore-servicing

agreement in place. The radio batteries were seen to be well maintained and in good condition and the EPIRB, SART and VHF handheld batteries were all in date as required. Berth to berth passage plans were seen on-board and were signed by all navigating officers with nautical publications provided in Paper and Electronic format. Master's standing and night orders were found to be signed by all navigating officers with the bridge log book correctly filled in and the GMDSS logbook also up to date and correctly filled in. The Monkey island was found to be in a good overall condition with the mast, aerials and antennas seen to be satisfactory and free of defects. It was also noted during that the inspection Annual radio survey and VDR annual performance test were in progress, with an Approved Radio surveyor and NK Class surveyor in attendance.

ENGINE ROOM AND MACHINERY

80

The Engine room and machinery were found to be in a good overall condition, with no significant defects reported or observed and with the engine room generally found to be very clean. During the inspection the Auxiliary Engines, purifiers, pumps, air compressors and sewage treatment plant were seen running. Bilges and tank tops were generally free of oil or water. Pipework was seen to be in good overall condition, free of leaks, temporary repairs and significant corrosion with pipework lagging seen to be all clean and intact. A review of the latest lube oil analysis reports provided showed some areas of concern as follows: 'Caution' warning noted from auxiliary engines 1 and 3 due to increased vanadium content, with it also noted that the last test was conducted in April 2022. The NOx Technical file was up to date and last updated on 02-Aug-22. The Main Engine was reported to be fully operational and was seen to be in good condition, with no major visible defects. A review of the latest Main Engine performance report provided showed no areas of concern. A review of the latest engine running hours showed that the Bearings and Cylinder Liners overhaul schedules are subject to Condition Based Monitoring (CBM) and therefore no dedicated overhaul

intervals are provided and Cylinder heads and Pistons overhauls were within the service hours. Propulsion systems, such as shafts, gearing and bearings were in good working order with no defects reported or sighted. The 3 Auxiliary Engines were reported to be fully operational and were seen to be in good condition, with no major visible defects. A review of the latest Auxiliary engines performance report provided showed some areas of concern as follows: reports do not record the engine load during the tests. A review of the latest Auxiliary engine running hours showed no overdue maintenance. The vessel's steam boiler was found to be fully operational and in good condition. The boiler safety valves were seen to be satisfactory and free of tampering. All Auxiliary equipment was found to be fully operational and in good condition. The steering gear was seen in good working order, free of leakage with emergency steering instructions seen to be posted nearby. The machinery spaces are operated in Unmanned mode and the alarm and control system was seen to be free of any serious alarms. Electrical distribution systems including the main switchboard were in good working order and switchboard insulation readings were adequate.

NOTABLE ITEMS

Description

Estimated Cost [USD]

Issue: The latest lube oil analysis reports showed 'Caution' warning noted from auxiliary engines 1 and 3 due to increased vanadium content, with it also noted that the last test was conducted in April 2022.

Corrective Action: The oils should be refreshed and re-tested as soon as possible. Oils with only a 'caution' warning are suitable for continued use.

<\$1000

FIRE FIGHTING EQUIPMENT AND SYSTEMS

80

Fire Fighting Equipment and Systems were found to be in a good condition overall and generally free of fire hazards with all firefighting equipment seen to be regularly serviced and inspected. The fire detection and alarm system was found to be fully operational and was free of signs of tampering and alarms. The vessel is fitted with Water Spray and CO2 fixed firefighting in the engine room, CO2 for the cargo areas and none in the accommodation. Fixed firefighting systems were all reported to be in good working condition with operating instructions clearly posted. The main and emergency fire pumps were reportedly fully operational and both were found to be in a good condition, free of leakages. A fire pump was tested during the inspection and was found to deliver adequate pressure. The fire main and ancillaries such

as hydrants and valves were in good overall condition, free of defects. Fire extinguishers were all in good condition and all portable equipment were positioned in accordance with the fire plan. Firefighting outfits and associated equipment were all in good condition with BA equipment found fully charged and ready for use. The emergency generator was tested during the inspection and found to be in good working order and in a good overall condition. Remote shutdown emergency devices such as quick closing valves, machinery stops and ventilation dampers were deemed to be in a good overall condition with no defective shut down equipment. The fire doors were found to be in good condition, closing effectively and free from any unauthorised 'hold-open' arrangements.

LIFESAVING APPLIANCES

80

Lifesaving appliances were seen to be in a good overall condition with all equipment regularly serviced and inspected as required. The vessel is fitted with 2 davit launched lifeboats, which were seen to be in good overall condition externally and internally. The lifeboat engines were tested during the inspection and found to be in good working order. The vessel has no dedicated rescue boat and uses the starboard lifeboat as a rescue boat. The vessel is equipped with 3 life rafts, which were found to be in good condition with Hydrostatic Release Units (HRUs) in date and correctly rigged. Davits and

lowering arrangements were found to be in good condition overall with evidence of regular maintenance, servicing and inspection sighted and evident. Ancillary lifesaving equipment such as lifejackets, immersion suits and EEBD's etc. were found to be in good condition and ready for immediate use with man overboard smoke and light signals seen to be in date. Embarkation ladders were found to be in a good, well maintained condition with the pyrotechnics and line throwing apparatus found to be stored appropriately and within their expiry dates.

SAFE WORKING ENVIRONMENT

80

Safe working was deemed to be good overall with no unsafe practices observed during the inspection and the vessel presenting a generally safe working environment. Hazards were seen to be clearly marked and external walkways adequately coated with non-slip paint and free of trip hazards. Adequate PPE was seen to be worn by crew at all times and portable gas detection meters were provided and calibrated. Hazardous substances were seen to be generally safely managed with appropriate Material Safety Data Sheets provided. Risk Assessments (RA)

were seen to be up to date and satisfactory with enclosed space entry procedures followed and an effective Permit To Work (PTW) system in place. Main and emergency exits were clearly identified and unobstructed with all IMO signage seen to be satisfactory. Pilot ladders and boarding arrangements were seen to be in a good safe condition with clear pilot boarding instructions posted. Regular drills were conducted on board with the last drill conducted on the 30-Sept-22, which was an MOB, recovery of person from water drill.

POLLUTION CONTROL

80

Pollution control was deemed to be good overall and generally found to be well implemented on board with the vessel free of pollution hazards.

The vessel holds a Class-approved Inventory of Hazardous Materials, which is required for entry into EU ports. The vessel's Oily Water Separator (OWS) was found to be fully operational and in good overall condition, with no obvious defects. The OWS was operationally tested during the inspection and the 15ppm Oil Content Meter (OCM) was seen to be calibrated. The bilge overboard was seen to be locked against unauthorised opening and the oily water treatment system as a whole was seen to be free from signs of tampering or unauthorised modification. The SOPEP locker was found to be well stocked with SOPEP equipment in good condition and an accurate list of equipment posted nearby. The Oil Record Book (ORB) was seen to be well-maintained and up-to-date, with the last entry on the 19-Sept-22. A US coastguard approved Ballast Water Treatment System (BWTS) is fitted and was found to be fully operational and in good overall condition. The vessel's

ballast record book was seen to be up to date and correctly filled in. The vessel is fitted with an Environmentally Acceptable Lubricant (EAL) in the stern tube and is therefore Vessel General Permit (VGP) compliant in this regard. The vessel's sewage treatment plant was found to be fully operational and in good overall condition, with no obvious defects. Garbage segregation was found to be good, with adequate, labelled containers and garbage seen to be well sorted and containers seen to be made of approved non-combustible materials. The Garbage Record Book (GRB) was seen to be well-maintained and up-to-date, with the last entry on the 14-Oct-22. The Emission Control Area (ECA) change-over logbook was reviewed and found to be satisfactory with the date of last entry on 13-Oct-22. The vessel's incinerator was found to be fully operational and in good overall condition, with no obvious defects. The vessel complies with IMO 2020 regulations by employing the use of Very Low Sulphur Fuels Oils (VLSFO) with a sulphur content of less than 0.5%.

NOTABLE ITEMS

Description

Estimated Cost [USD]



Issue: A US coastguard approved Ballast Water Treatment System (BWTS) is installed.

Corrective Action: Positive.

\$0

Description

Estimated
Cost
[USD]

Issue: The vessel is fitted with an Environmentally Acceptable Lubricant (EAL) in the stern tube and is therefore Vessel General Permit (VGP) compliant in this regard.

Corrective Action: Positive.

\$0

ONBOARD MANAGEMENT

80

Onboard management was found to be good overall. The computer-based Safety Management System (SMS) was deemed to be functioning and well implemented in general, with Permits to Work (PTW), risk assessments and procedures understood and followed. Onboard management was found to deal with accidents, near misses and deficiencies in an effective manner and regular safety committee meetings were carried out on board. The vessel's MLC certificate was valid with records of hours of rest (ILO) correct and up to date and maximum work hours not regularly exceeded. The PMS system was found to be kept up to date with no critical overdue work orders. The Class-approved system-based Planned

Maintenance System (PMS) was not fully integrated with the SMS for ordering of spares and general vessel management. The Port State Control (PSC) history was found to be good with 21 deficiencies and 0 detentions in the 14 inspections conducted in the past three years. The vessel's flag is not targeted by any Memorandum of Understanding (MoU) or the USCG. Security access controls were deemed to be satisfactory with the vessel conforming to International Ship and Port Security (ISPS) standards. The Master and crew were prepared for the inspection and provided good cooperation with the majority of requested documents provided.

VESSEL CAPABILITIES AND CARGO SYSTEMS

80

Vessel capabilities and cargo systems were deemed to be in a good overall condition. All 5 holds entered as far as practical due to on-going cargo operations, however no photographs of previous hold entries were provided for review. Cargo hold structural members were found to be free of damage as were hold fixtures, such as ladders, hand rails etc. The inspected Cargo Holds had only minor localised and spot corrosion, up to approximately 2% of the hold surface area, mainly located to corrugated bulkheads. The last cargo carried was aluminum ingots, with the next intended cargo reported to be not yet known. The holds were free of signs of water ingress and bilges were seen to be clean, dry and free of any debris. The vessel is fitted with hydraulic folding hatch covers, which were seen to be well aligned and closing correctly. Hatch covers were found to be free of structural defects and had only minor scattered spot corrosion, up to approximately 5% of the hatch cover surface area, mainly located to top sides and lower side edges with signs of on-going cosmetic maintenance noted. Hatch cover operating systems were in full working order but were seen to be in fair condition with areas of corrosion noted to wheels, hinges, hydraulic cylinders as well as a leak noted from the port forward cylinder for hatch number 4. Hatch cover rubber seals and retaining channels were in good overall condition with hold-open arrangements also in good condition. Landing pads in good condition with no excessive wear visible or reported with hatch cover securing arrangements also in good condition. In addition, the holds were also free of signs of internal leaks. Hatch coamings were found to be free of structural defects and had only minor localised surface corrosion, up to approximately 3% of the hatch coaming surface area, mainly located in difficult to maintain areas, underside of stiffeners, and on edges of brackets. Compression bars/strips were seen to be in good

condition with hatch coaming drain channels free of corrosion, scaling and debris and the hatch coaming non-return valves clear and operational. The vessel has a Document of Compliance (DOC) for the carriage of dangerous goods and a Document of Authority (DOA) to carry grain. The approved cargo loading manual and stability booklet were found to be on board. Stability calculations were seen to be carried out, and the vessel is equipped with a Class-approved computer based stability software. No movable bulkheads or tween decks were carried on board. Cargo securing fittings were found to be in good condition. The vessel is not equipped to carry Reefer containers. The vessel has 4 cargo lifting appliances, which were found to be in a good overall condition. Lifting appliances were found to be generally free of significant structural defects and had only minor localised, surface and spot corrosion, up to approximately 10% of the surface area, mainly located on jibs, inspection platforms, around slewing bearings, around operator cabins, and to pedestal. Wires were in good overall condition as were motors and hydraulic systems, which were free of defects and leaks. Lifting appliances components, such as sheaves, blocks and cylinders were seen to be in a good overall condition with controls and operating positions in good condition and safety devices fully operational. The slewing bearings were found to be in a fair overall condition with some corrosion around bearings and on bolts (external), more so to crane number 1. Lifting appliances were regularly examined by shore side technicians with maintenance records accurate and up-to-date. It was also noted the vessel is equipped with 3 hydraulic operated grabs, maker Guven. They were seen to be in a good overall condition, free of any areas of damage or deformation with minor spot corrosion noted. However, no information was available as to when they were last in use.

NOTABLE ITEMS

Description

Estimated
Cost [USD]**Issue:** A leak was noted from the port forward cylinder for cargo hatch cover number 4.**Corrective Action:** To be further investigated and rectified as soon as practical.

<\$1000



OPERATIONAL DATA

Operational Data Condition

Does the vessel have an Exhaust Gas Cleaning System (EGCS)? ☒ No

Total High Sulphur Fuel Oil (HSFO) capacity:	m ³
Total Very and Ultra Low Sulphur Fuel Oil (VLSFO and ULSFO) capacity:	1,593.4 m ³
Total Marine Gas Oil (MGO) and Diesel Oil (DO) capacity:	422.9 m ³
Total Fresh Water capacity:	541.8 m ³
Total Ballast Capacity Excluding Cargo Hold Ballast Capacity:	16,032.4 m ³
Total Bilge water capacity:	22 m ³
Total sludge and residues capacity:	26.3 m ³

What fuel type does the vessel run on for the majority of the time?	Heavy Fuel Oil (HFO)
---	----------------------

Does the vessel have any energy efficiency technologies installed? ☒ No

Engines Table

	Main Engine 1	Main Engine 2	Aux Engine 1	Aux Engine 2	Aux Engine 3	Aux Engine 4
Designer	MAN B&W	N/A	Yanmar	Yanmar	Yanmar	N/A
Model	MC-C		6EY18L	6EY18L	6EY18L	
Mark/Series/Revision	7					
Number of Cylinders	6		6	6	6	
Speed (RPM)	121		720	720	720	
Bore (mm)	500		180	180	180	
Stroke (mm)	2,000		280	280	280	
Specific Fuel Oil Consumption (SFOC) (g/kWhr) At 75% load for ME and 50% load for AEs, corrected to ISO conditions, as stated on Nox technical files	169.4		215	215	215	
Nox Tier	1		1	1	1	
Fuel Oil Consumption at full load (tonnes/day)	27.4		1.3	1.3	1.3	
Cylinder Oil Consumption (litres/day)	145					
System Oil Consumption (litres/day)	8		4	4	4	

Major Overhaul Interval (Hours)			10,000	10,000	10,000	
Running Hours since last overhaul (Hours)			10,000	10,000	10,000	

	Vessel Speed (knots)	Consumption (t/day)
Loaded Eco	12	19.5
Loaded Service	13	23
Ballast Eco	12	17.95
Ballast Service	13.5	22

Main Engine Maintenance

Component	Condition Based Monitoring?	Overhaul Interval
Cylinder Heads		12,000
Pistons		12,000
Bearings	Yes	
Cylinder Liners	Yes	12,000

Main Engine No.1

Unit Running Hours

	1	2	3	4	5	6	7	8	9	10	11	12
Cylinder Heads	6,585	3,996	5,720	2,522	6,585	6,733						
Pistons	6,585	3,996	5,720	2,522	6,585	6,733						
Bearings	3,699	3,699	3,699	3,699	3,699	3,699						
Cylinder Liners	51,565	51,565	51,565	51,565	51,565	51,565						

Class Surveys

Were all Class and Statutory certificates valid? ☒ Yes

Is the vessel on the Extended Dry Docking (EDD) program? ☒ No

Is the vessel on the Enhanced Survey Program (ESP)? ☒ No

Does the vessel have an In Water Survey Class notation? ☒ Yes

Is the vessel ice classed? ☒ No

Survey	Date Last Completed	Date Next Due
Main / Special / Renewal	24-Dec-21	07-Nov-26
Intermediate		07-Feb-24
Annual	19-Oct-22	07-Nov-23
Bottom In Water		23-Dec-24
Bottom in dry dock	24-Dec-21	07-Nov-26

What was the location of the last out-of-water docking?

Onex Syros shipyard Greece

Is the vessels last dry dock report provided and attached?

☒ Yes

Does the vessel intend to dry dock before the next scheduled bottom survey?

☒ No

Has the vessel remained with the same flag since build?

☒ No

Please provide details of previous flags

Marshall Islands, Singapore, Panama

Has the vessel remained with the same Class since build?

☒ Yes

Does the vessel have any Conditions of Class or Recommendations of Class?

☒ No

Does the vessel have any Class Memos, Observations or Additional Requirements?

☒ Yes

Please provide further details

Retroactive requirement: Marpol annex VII regulation 14.10 - sampling points shall be fitted not latter than the first renewal survey of IAPP certificate on or after 01 April 2023.

The cost for the next out of water bottom survey or dry docking based on a far eastern shipyard and includes all survey and normal maintenance costs is approximately estimated at:

900,000

What was the status of the vessel at the time of inspection?

Discharging

DESIGN AND CONSTRUCTION

Design and Construction Condition

Has the vessel been built to the standards and Rules of an IACS-member Class Society?

☒ Yes

Under what IACS Class society supervision was the vessel built?

NK - ClassNK

Did the vessel provide Ultrasonic Thickness Measurement (UTM) reports?

Yes

Did the UTM report show any diminution of steelwork?

Minor

Please provide further details

The latest UTM report provided showed minor levels of steel diminution.

Hull & Structure

Bridge & Communication

What features were seen on the bridge?

☒ Differential-GPS

JRC - JLR 7,800 - two units

Engine Room & Firefighting

☒ Incinerator sludge burning system

Sunflame

☒ UMS Capabilities (regardless of Class notation)

vessel operates on UMS mode

☒ 2-Stroke Engine Adaptive Cylinder Oil Control e.g.
MAN B&W Alpha Lubricator

originally fitted alpha lubricators

HULL

Hull Condition

What sections of the hull were inspected?

All round (alongside)

Was the vessel free of any major structural damage or indentations?

☒ Yes

Was the vessel free of any minor structural damage or indentations?

☒ Yes

What was the level of Hull coating breakdown and corrosion?

Minor

Coating breakdown and corrosion was mainly located in the following areas:

to midships boot top area

The amount of surface area coating breakdown and corrosion was approximately:

2%

Type of coating breakdown and corrosion:

☒ Localised☒ Spot

What was the condition of the hull markings?

Well painted and clearly legible

What type of anti-fouling coating was applied?

Chugoku paints: Sea grandprix 880 HS

What level of marine fouling was seen?

Minor

Were fenders installed on the hull?

☐ No

What were the vessels draughts?

Fwd: (m)	7.4
Aft: (m)	7.8

Was the upper sections of the rudder visible?

☒ No

MOORING DECKS

Mooring Decks Condition

Were the decks free of any structural damage or deformations?

☒ Yes

What was the level of coating breakdown and corrosion observed on the decks?

Minor

Coating breakdown and corrosion was mainly located in the following areas:

to deck plating and around foundations of mooring equipment

The amount of surface area coating breakdown and corrosion was approximately:

2%

Type of coating breakdown and corrosion:

☒ Localised☒ Surface

What was the general condition of the deck fittings?

Good

Were fairleads and mooring rollers free to move when tested?

☒ Yes

Were all mooring machinery reported to be fully operational?

☒ Yes

What type of windlass(es) and winches were fitted?

Hydraulic

Were the windlass(es) and winches seen to be free of hydraulic oil leaks?

☒ Yes

Was the mooring machinery hydraulic pump unit (HPU) seen to be free from leaks?

☒ Yes

What was the condition of the mooring machinery?

Good

What amount of band brake lining was seen to be remaining?

Substantial

Were clutching and gearing arrangements sufficiently greased?

☒ Yes

What condition were the visible sections of the anchor chains seen to be in?

Good

What type of mooring lines did the vessel have?

Rope

What was the condition of the mooring ropes / wires?

Good

Were safe mooring practices observed? i.e. no overlapping turns on split drum, chafing of lines or unsafe leading.

☒ Yes

Was the last brake test seen to be stencilled on the mooring winches?

☒ No *not sighted*

What type of snap back warning signs/zones were posted?

Signs at the entrance to the mooring decks

Was the Bosun's / Foc'sle store available for inspection?

☒ Yes

What was the condition of the bosun's store structure?

Structurally sound with no visible damage

What was the condition of the bosun's store coatings?

Coatings fully intact with no corrosion

Was the condition of the bosun's store housekeeping?

Fairly neat with some scattered equipment

Were the bitter end release arrangements seen to be clear and unobstructed?

☒ Yes

Was an 'emergency towing booklets/procedures'
available near to the foc'sle?

☒ Yes

WEATHER DECKS AND FITTINGS

Weather Decks and Fittings Condition

Were the decks free of any structural damage or deformations?

☒ Yes

What was the level of coating breakdown and corrosion observed on the decks?

Minor

Coating breakdown and corrosion was mainly located in the following areas:

to deck walkways and cross deck areas

The amount of surface area coating breakdown and corrosion was approximately:

5%

Type of coating breakdown and corrosion:

☒ Localised☒ Spot☒ Surface

What was the general condition of the deck fittings e.g handrails, brackets, vent heads, walkways, lighting etc.?

Fair

Please provide further details

localised areas of corrosion noted to pipework fittings and supports

Does the vessel have mooring winches fitted on the main deck?

☒ No

Were deck equipment and pipework free of leakages?

☒ Yes

What was the condition of the accommodation ladders or gangways?

Fair

Please provide further details

scattered areas of corrosion noted to the starboard side accommodation ladder

Was the vessel fitted with a provision lifting appliance(s)?

☒ Yes

What was the condition of the provision lifting
appliance(s)?

Good

Does the vessel carry any major spares on external
decks e.g. propeller blades, anchor etc.

☒ No

BALLAST TANKS AND SYSTEMS

Ballast Tanks and Systems Condition

Were ballast tanks entered?

☒ Yes

Please provide further details

Tanks Entered: Fore peak, and Number 5 Port and Starboard

Were recent (last 12 months) ballast tank inspection photographs provided?

☒ No

Were inspection reports or reports of the tanks condition provided?

☒ Yes

Were the tanks free of any structural damage or indentations?

☒ Yes

What was the level of Ballast Tank coating breakdown and corrosion?

Minor

Coating breakdown and corrosion was mainly located in the following areas:

to the bulkheads and edges of supports in the fore peak, as well as localised areas of corrosion noted to the bulkhead adjacent to the cargo hold in tank 5 port

The amount of surface area coating breakdown and corrosion was approximately:

5%

Type of coating breakdown and corrosion:

☒ Localised

☒ Surface

☒ Spot

Were ballast tanks coatings certified to PSPC standards?

☒ No

What was the condition of ballast tank fittings (e.g. ladders, handrails, pipes & manhole seals)?

Good

Were the ballast tanks fitted with sacrificial anodes?

☒ Yes

Anode depletion:

15%

How much mud/sediment was seen inside the ballast tanks?

Minimal

Please provide further details

%

Were the tanks seen to be free from any signs of staining from oil, sewage or marine fouling?

☒ Yes

Were ballast tank manhole covers seen to be in good condition?

☒ Yes

Were the remote ballast control systems fully operational (e.g. valves, gauging etc)?

☒ Yes

Were the ballast and/or anti-heeling pumps reported to be fully operational?

☒ Yes

What condition were the ballast and/or anti-heeling pumps in?

Good

ACCOMMODATION

Internal Accommodation Condition

Were accommodation spaces used for their assigned purposes? ☒ Yes

What was the condition of the flooring and wall coverings?

Good

What was the condition of the upholstery and furniture?

Good

What were the general levels of housekeeping and cleanliness?

Good

What was the level of hygiene of the sanitary facilities?

Fair

Please provide further details

cleanliness could be improved in the common sanitary facilities for the crew

Was all laundry equipment in good working order? ☒ Yes

Was the Hospital well equipped and ready for use? ☒ Yes

Were the drugs controlled and substances seen to be locked away? ☒ Yes

Was the associated drugs log kept up to date? ☒ Yes

What was the quality of accommodation outfitting?

Average quality of outfitting

Did the Air Handling Unit (AHU) maintain a comfortable temperature? ☒ Yes

What was the condition of the AHU?

Good

Galley Condition

What was the level of cleanliness in the Galley?

Clean

Was all galley equipment operational?

☒ Yes

What was the general condition of galley equipment?

Good

Were the insides of Galley hoods clean?

☒ Yes

What type of cold provisions stores does the vessel have?

Walk-in stores / Cold rooms

Were provisions stores well organised with no provisions stored directly on the deck?

☒ Yes

Were provisions stores clean and hygienic?

☒ Yes

Were provisions stores at the required temperatures?

☒ Yes

Were provision stores temperatures recorded and records kept nearby?

☒ Yes

Were provisions machinery, pipework and door seals free of frosting and deterioration?

☒ No*accumulation of ice note around pipework in the meat room*

Were lock-in alarms or handles in good working condition?

☒ Yes

External Areas Condition

Was the external Superstructure / Accommodation Block found to be free from damages?

☒ Yes

Were accommodation external doors found to be in good condition and providing an adequate seal?

☒ Yes

What was the level of external accommodation superstructure coating breakdown and corrosion?

None

What was the general condition of external superstructure fittings?

Fair

Please provide further details

localised areas of corrosion noted to the air condition room manhole cover located next to the CO2 room entrance

Crew Welfare

What is the average contract length for crew members?

Officers:

7 Months

Crew:

9 Months

Was Wi-Fi provided on-board?

Yes. Paid, Limited

What is the approximate average internet speed?

Average (Able to access social media apps and websites with ease)

Is access provided to catering facilities or food at all times?

☒ Yes

What Public Recreation equipment did the crew have access to?

☒ Cycling Machine

☒ Table Tennis

☒ Karaoke

☒ Entertainment Library - Books, DVDs, Games, etc.

☒ Public Computer

What was the quality of crew recreation facilities?

Poor

Crew recreation facilities were to a fair/poor standard due to:

very minimal recreation equipment available on board. gymnasium room almost no equipment furnished, the room not used for its intended purpose.

Are crew given time and resources to celebrate religious or cultural events (i.e. Christmas, Independence days etc.)?

☒ Yes

What facilities were provided in crew cabins?

☒ Sofa

☒ Desk

☒ Ample storage

Does the vessel have any onboard training facilities?

Yes

Type of onboard training facilities:

☒ Seagull

Is there a crew suggestion policy in place?

☒ Yes

Does the crew have access to a bonded store?

Yes, well stocked

Are the crew given additional periods of rest throughout the working week (e.g Sunday off)?

Yes

BRIDGE AND NAVIGATION EQUIPMENT

General Condition

Was all the bridge equipment reported to be fully operational? ☒ Yes

Was the bridge found to be clean and well maintained with good housekeeping? ☒ Yes

Was the view from the bridge clear and unobstructed? ☒ Yes

Were all required bridge equipment annual performance tests (e.g. VDR and AIS) completed in the last 12 months? ☒ Yes

Was the vessel fitted with a Voyage Data Recorder (VDR)? ☒ Yes

Type of VDR fitted:

VDR

Was the VDR seen to be free from any unanticipated alarms? ☒ Yes

Were the VDR collection instructions posted and known to the Master? ☒ Yes

Was the vessels Bridge Navigation and Watch Alarm System (BNWAS) fully operational, and turned on when at sea? ☒ Yes

Normal time setting at sea

12 mins

Navigation Condition

	Primary	Secondary
What was the vessels primary & secondary means of navigation as listed on Form E?	ECDIS	ECDIS

Were the primary & secondary means of navigation found to be up to date?

☒ Yes

Latest update week

41

Was the Echo Sounder fully operational?

☒ Yes

Were the RADARs fully operational?

☒ Yes

Were the "blind sectors" posted near to the RADARs?

☒ Yes

Does the vessel receive up to date weather information?

☒ Yes

19-Oct-22

What type of weather updating service does the vessel use?

Weather fax

Was an in-date compass deviation card posted near to the helm?

☒ Yes

Was a compass deviation log kept, up to date and free of any major deviations?

☒ Yes

Were azimuth rings (bearing diopters) found to be available on the bridge?

☒ Yes

Communication Condition

What GMDSS sea areas was the vessel licensed to cover?

☒ A1

☒ A2

☒ A3

☒ A4

Were the radio batteries seen to be in good condition?

☒ Yes

Were the EPIRBs, SARTs and Emergency Hand Held VHF Batteries within their expiry dates?

☒ Yes

Battery expiry dates

EPIRBs

31-Oct-24

SARTs

30-Jun-25

VHF

30-Nov-23

Was a valid GMDSS shore servicing certificate seen to be posted near to radio equipment?

☒ Yes

Documentation Condition

Were berth to berth passage plans seen on-board?

Yes

Were passage plans signed by all navigating officers?

☒ Yes

What format were nautical publications provided in?

Paper and Electronic

Were the Master's standing orders and night orders found to be signed by all navigating officers?

☒ Yes

Was the bridge log book up to date and correctly filled in?

☒ Yes

Was the GMDSS log book up-to-date and correctly filled in?

☒ Yes

Date of last test

18-Oct-22

External Condition

Was the Monkey Island found to be in good, well maintained condition?

☒ Yes

Were the main mast, aerials and antennas seen to be in good condition and free from damage?

☒ Yes

Were bridge wing manoeuvring controls fitted?

☒ No

Were bridge wing engine speed and compass repeaters seen to be in good working condition?

☒ Yes

ENGINE ROOM AND MACHINERY

General Condition

What equipment was seen running?

- | | |
|--|--|
| <input checked="" type="checkbox"/> Auxiliary Engines | <input checked="" type="checkbox"/> Purifiers |
| <input checked="" type="checkbox"/> Pumps | <input checked="" type="checkbox"/> Air compressors |
| <input checked="" type="checkbox"/> Sewage treatment plant | <input checked="" type="checkbox"/> Auxiliary Boiler |
| <input checked="" type="checkbox"/> Refrigeration Compressor | |

Was the engine room free of any significant defects, either reported by crew or observed?

- ☒
- Yes

What was the general cleanliness of the Engine Room?

Very Clean

Were bilges and tank tops free of oil and water?

- ☒
- Yes

Was housekeeping to a good overall standard?

- ☒
- Yes

Was the vessel equipped with adequate critical spares as recommended by the ship manager Safety Management System (SMS)?

- ☒
- No

not provided for review

Were spares neatly stowed and correctly secured?

- ☒
- Yes

Were all sounding pipe self-closing devices in good working order and sounding pipes capped?

- ☒
- Yes

Were recent copies of lube oil analysis reports provided for review?

- ☒
- Yes

Were any caution (amber) or action (red) alerts seen on the lube oil analysis reports?

- ☒
- Yes

'Caution' warning noted from auxiliary engines 1 and 3 due to increased vanadium content, with it also noted that the last test was conducted in April 2,022.

Was the NOx Technical file kept up to date?

- ☒
- Yes

Date of entry:

02-Aug-22

Were Chief Engineer Standing Orders clearly posted and signed by all engineers?

☒ Yes

Were all machinery special tools provided and in good condition?

☒ Yes

Main Engine Condition

Was the main engine in good working condition?

Yes

What condition did the Main Engine appear to be in?

Good

Were Main Engine performance reports provided for review?

☒ Yes

Were the performance reports satisfactory?

☒ Yes

Was there any overdue maintenance on the Main Engine Turbochargers?

☒ No

Propulsion

What type of propulsion does the vessel have?

Fixed Pitch Propeller (FPP)

Were the Propulsion systems, including shafts, machinery and electric motors, if relevant, in good working condition?

☒ Yes

What type of thruster systems does the vessel have?

☒ None

Power Generation

How many Auxiliary Engines does the vessel have?

3

Were the auxiliary engines in good working condition?

☒ Yes

What condition did the Auxiliary Engines appear to be in?

Good

Were Auxiliary Engines performance reports provided for review?

☒ Yes

Were the performance reports satisfactory?

☒ No

reports do not record the engine load during the tests

Does the vessel have a shaft generator?

☒ No

Does the vessel have a shaft motor (Power Take-In)?

☒ No

Auxiliary Machinery

Does the vessel have an Auxiliary Boiler?

☒ Yes

What type of boiler is fitted?

Steam

Was the boiler in good working condition?

☒ Yes

What condition did the Boiler appear to be in?

Good

Were boiler safety valves in satisfactory condition?

☒ Yes

Equipment	Fully operational?	Condition
Purifiers	Yes	Good
Pumps	Yes	Good
Coolers	Yes	Good
Air Compressors	Yes	Good
Fresh Water Generator	Yes	Good
Filters	Yes	Good
Fans	Yes	Good
Refrigeration Systems	Yes	Good

Was all engine room pipework free of leakages? ☒ Yes

Was all pipework free of temporary repairs? ☒ Yes

Was all pipework free of corrosion or soft patches? ☒ Yes

What condition was pipework lagging in?	Clean
---	-------

Was the steering gear in good working condition? ☒ Yes

Was the steering gear free of leakages? ☒ Yes

Was the emergency steering communication equipment and gyro repeater working as required? ☒ Yes

Were emergency steering instructions posted nearby? ☒ Yes

Was the Engine workshop clean and tidy? ☒ Yes

ECR and Electrical

- | | |
|--|---|
| Was the Engine Control Room clean and tidy? | <input checked="" type="checkbox"/> Yes |
| Was the Engine Control and Alarm system free of any serious alarms? | <input checked="" type="checkbox"/> Yes |
| Does the vessel have an Unmanned Machinery Space (UMS) notation? | <input checked="" type="checkbox"/> Yes |
| Does the machinery space operate in UMS mode? | <input checked="" type="checkbox"/> Yes |
| Were all Electrical distribution systems in good working condition? | <input checked="" type="checkbox"/> Yes |
| Were Main Switchboard Insulation readings adequate? | <input checked="" type="checkbox"/> Yes |
| Were distribution and switchboard panels protected with approved rubber matting? | <input checked="" type="checkbox"/> Yes |

FIRE FIGHTING EQUIPMENT AND SYSTEMS

Fire and Safety Appliances Condition

Was the vessel free of fire hazards? ☒ Yes

Was all fire and safety equipment regularly serviced? ☒ Yes

Date of last service

19-Oct-22

Were all relevant Fire and Safety instructions correctly posted? ☒ Yes

What was the vessels Fixed fire detection systems?

Engine Room

Cargo Holds

Accommodation

☒ Flame

☐ Flame

☐ Flame

☒ Smoke

☐ Smoke

☒ Smoke

☒ Heat

☐ Heat

☒ Heat

☐ Smoke & Heat
(Combined)

☐ Smoke & Heat
(Combined)

☐ Smoke & Heat
(Combined)

Was the fire detection system reportedly fully operational? ☒ Yes

Was the fire detection system free of alarms or signs of tampering? ☒ Yes

What is the vessels Fixed firefighting systems?

Engine Room**Cargo Holds****Accommodation**☒ CO2☒ CO2☒ Water Mist☒ Foam☒ Deck Foam☒ Galley CO2☒ Water Spray☒ Water Spray☒ Wet Chemical☒ None☒ None☒ None

Were all fixed fire fighting systems in good working condition?

☒ Yes

Were clear operating instructions posted for the fixed firefighting systems?

☒ Yes

Was the fixed firefighting system release protected against unauthorised operation?

☒ Yes

Was the main fire pump working?

☒ Yes

Was the emergency fire pump working?

☒ Yes

Was a fire pump tested during the inspection?

☒ Yes

Did the fire pump maintain adequate pressure?

☒ Yes

Were the main and emergency fire pumps in good condition and free of leakages?

☒ Yes

What was the condition of the fire main and ancillaries such as pipework hydrants and valves?

Good

Does the vessel have a fire control station?

☒ Yes

Were all portable equipment in place as per the fire plan?

☒ Yes

Were all fire extinguishers in good condition?

☒ Yes

Were the firefighting outfits and associated equipment in good condition?

☒ Yes

Were the International Shore Connections on board?

☒ Yes

Location:

upper deck - fire station

Was the BA equipment fully charged in good condition?

☒ Yes

Was the Emergency Generator tested during the inspection?

☒ Yes

Was the Emergency Generator in working order?

☒ Yes

Were Emergency Generator Starting instructions clearly posted?

☒ Yes

What was the condition of the Emergency Generator?

Good

Was the "18 hour" fuel level marked on the emergency generator fuel tank?

☒ Yes

Was the Quick Closing Valve system in good working order?

☒ Yes

Were fire doors in good condition and effectively closing?

☒ Yes

Were fire doors free of unauthorised "hold-open" arrangements?

☒ Yes

Were all ventilation dampers remote closing positions well labelled and in good working order?

☒ Yes

Were all remote machinery shutdown systems well labelled and in good working order?

☒ Yes

LIFESAVING APPLIANCES

Lifesaving Appliances Condition

Were all Lifesaving Appliances regularly serviced? ☒ Yes

Date of last service:

19-Oct-22

How many lifeboats is the vessel equipped with?

2

What type of lifeboat is the vessel fitted with?

Davit launched

What was the external condition of the lifeboat(s)?

Good

What was the internal condition of the lifeboat(s)?

Good

Were Lifeboat Engines able to be tested? ☒ Yes

Were lifeboat engines in good working order? ☒ Yes

What type of rescue boat was fitted?

Lifeboat designated as rescue boat

Which lifeboat is designated?

Stbd

How many life rafts does the vessel have?

3

What was the condition of the life rafts?

Good

Were Liferaft Hydrostatic Release Units (HRU) in date and correctly rigged?

☒ Yes

What was the condition of the Davits and lowering arrangements for the lifeboat(s), rescue boat and liferafts?

Good

What Date is the next Davit wire due for change?

31-Aug-26

Were legible launching/recovery instructions posted near to survival craft?

☒ Yes

Was evidence of regular maintenance, service and inspection of the launching appliances sighted and evident?

☒ Yes

What was the date of the last abandon ship drill?

15-Sept-22

Were all lifejackets, immersion suits, EEBDs and other lifesaving ancillary equipment in good condition and ready for use?

☒ Yes

Were Man Overboard Buoy (MOB) smoke and light signals in date?

☒ Yes

Were the embarkation ladders in a good, well maintained condition?

☒ Yes

Were pyrotechnics and line throwing apparatus available, stored in an appropriate container and within their expiry dates?

☒ Yes

SAFE WORKING ENVIRONMENT

Safe Working Environment Condition

- Were any unsafe practices observed during the inspection? ☒ No
- Did the vessel provide a safe working environment? ☒ Yes
- Were all hazard markings clear? ☒ Yes
- Were external walkways adequately coated with anti-slip paint and free of trip hazards? ☒ Yes
- Are all hazardous substances including safely managed and stored with relevant Material Safety Data Sheets (MSDS)? ☒ Yes
- Is Personal Protective Equipment (PPE) provided and worn by crew? ☒ Yes
- Are 'Enclosed Space Entry' procedures implemented? ☒ Yes
- Is an effective Permit To Work (PTW) process implemented? ☒ Yes

Date of last PTW:

19-Oct-22

- Is an effective Risk Assessment (RA) process in place? ☒ Yes
- Was evidence of the annual and 5-yearly inspections of both fixed and portable lifting equipment and appliances sighted? ☒ Yes
- Are main and emergency exits clearly identified and unobstructed? ☒ Yes
- Are sufficient portable oxygen and gas detection meters provided and regularly calibrated? ☒ Yes

Date of last calibration:

13-Oct-22

What is the working language of the vessel?

English

Are standing orders, procedures, instructions and manufacturers' manuals written in a language which can be understood by the crew?

☒ Yes

Are all IMO signs correctly placed, and compliant with IMO requirements?

☒ Yes

Does the vessel have an adverse history of accidents and near-misses?

☒ No

Is the vessel equipped with an approved SOLAS training manual?

☒ Yes

Were the pilot ladders and boarding arrangements in a good, safe condition?

☒ Yes

Does the vessel have clear pilot boarding instructions posted?

☒ Yes

Are regular drills conducted on board?

☒ Yes**Last drill date**

30-Sept-22

Last drill type

MOB, recovery of person from water

POLLUTION CONTROL

General Condition

Was Pollution Control well implemented within the on board Safety Management System (SMS)? ☒ Yes

Is the vessel free of pollution hazards?

Yes, with no hazards

Were scuppers plugged in port as required? ☒ Yes

Does the vessel have a Class approved Inventory of Hazardous Materials (IHM)? ☒ Yes

The vessel holds a Class approved Inventory of Hazardous Material (IHM)

Oil - Marpol Annex I

Is an Oily Water Separator (OWS) fitted? ☒ Yes

Was the OWS reportedly operational? ☒ Yes

What was the condition of the OWS?

Good

Was the OWS Tested? ☒ Yes

Means of testing

Operational

Was the 15ppm meter calibrated? ☒ Yes

Date of calibration

20-Nov-17

Was the Bilge Overboard valve secured against unauthorised opening with adequate signage and warnings posted? ☒ Yes

Means of securing ☒ Locked

Was the oily water treatment system including valves and pipework free of any signs of tampering, bypass, or modifications?

☒ Yes

Was the SOPEP locker or box well stocked?

☒ Yes

What was the condition of the SOPEP equipment?

Good

Was a list of SOPEP equipment posted and accurate?

☒ Yes

Was the Oil Record Book (ORB) up to date and correctly filled in?

☒ Yes

Date of last entry

19-Sept-22

Category of last entry

D

Were previous bunkering checklists correctly filled out?

☒ Yes

Date of last bunkering

06-Oct-22

Were bunker samples correctly stored?

☒ Yes

Does the vessel have a Ballast Water Treatment System (BWTS) fitted?

☒ Yes

Ballast Water Treatment System

Manufacturer:

Techcross

Type:

Electrolysis

What regulation is listed on the Ballast Water Management Certificate?

D-2

Type of BWTS approval:

USCG approval

Was the BWTS operational?

☒ Yes

What was the condition of the BWTS?

Good

Was the Ballast Record Book up to date and correctly filled in?

☒ Yes

Date of last entry

18-Oct-22

Is the Vessel General Permit (VGP) compliant?

☒ Yes

Due to the use of an EAL or the airseal arrangements in place for the stern tube, the vessel is considered VGP compliant in this regard for trade to the USA

How is the vessel VGP Compliant? *Environmentally Acceptable Lubricant

☒ Stern Tube EAL

Type of EAL

Gulfsea BD stern tube 100

Sewage - Marpol Annex IV

Was a Sewage Treatment Plant fitted?

☒ Yes

Was the Sewage Treatment Plant operational?

☒ Yes

What was the condition of the Sewage Treatment Plant?

Good

Does the vessel have a sewage holding tank?

☒ No

Garbage - Marpol Annex V

Does the vessel have a garbage management plan?

☒ Yes

How was the condition of Garbage segregation?

Good

Were Garbage containers of approved, non-combustible type?

☒ Yes

Was the Garbage Record Book (GRB) up to date and correctly filled in?

☒ Yes

Date of last entry

14-Oct-22

Category of last entry

E

Air - Marpol Annex VI

Does the vessel have a valid IAPP certificate?

☒ Yes

Is the vessel compliant with IMO 2,020 Sulphur cap regulations?

☒ Yes

How does the vessel comply with IMO 2,020 regulations?

Use of Very Low Sulphur Fuel Oils (VLSFO), MGO, DO etc.

Does the vessel use Ozone Depleting Substances (ODS) as Refrigerant Gas?

☒ No

Was an Incinerator fitted?

☒ Yes

Was the Incinerator operational?

☒ Yes

What was the condition of the Incinerator?

Good

Does the vessel have an Emission Control Area (ECA) change-over log?

☒ Yes

Date of last entry

13-Oct-22

EEXI

Does the vessel have an EEDI score assigned at build?

☒ Yes

What is the EEDI score?

6.29

What fuel type does the vessel run on for the majority of the time?

Heavy Fuel Oil (HFO)

Does the vessel have any energy efficiency technologies installed?

☒ No

Is the vessel ice classed?

☒ No

Main Engine(s)

Specific Fuel Oil Consumption (SFOC) (g/kWhr):

169.4

Auxiliary Engines

Specific Fuel Oil Consumption (SFOC) (g/kWhr):

215

Does the vessel have a shaft motor (Power Take-In)?

☒ No

What is the expiry date of the International Air Pollution Prevention (IAPP) certificate?

07-Nov-26

Year

What were the vessel's CII scores (From the IMO DCS data)? (gramsCO₂/ton.Nautical mile)

2021

6.55

2020

7.26

ONBOARD MANAGEMENT

Onboard Management Condition

Does the vessel have a functioning Safety Management System (SMS)? ☒ Yes

How was the SMS Implemented?

Software / Electronic System

Were the officers familiar with, and allowed easy access to, the SMS? ☒ Yes

Was the SMS well implemented on board, with Permits to Work, Risk Assessments and Safety procedures understood and followed? ☒ Yes

Is the SMS system regularly reviewed by the Master? ☒ Yes

Date of last review

30-Sept-22

Does the vessel management deal with accidents, near-misses and deficiencies in an effective manner? ☒ Yes

Are regular safety committee and management meetings carried out on board? ☒ Yes

Does the vessel have a valid MLC certificate? ☒ Yes

Were Hours of Rest (ILO) records correct and up to date? ☒ Yes

Last updated

18-Oct-22

Are hours of maximum permissible work regularly exceeded? ☒ No

Is an effective Planned Maintenance System (PMS) implemented and kept up to date? ☒ Yes

What type of Planned Maintenance System (PMS) does the vessel have?

Class-approved system

Name of PMS

Task assistant

Was the PMS a fully integrated type system? (i.e. has integration with the SMS, spares ordering and is accessible by shore side management)

☒ No

Were there any critical overdue PMS work orders?

☒ No

Port State Control (PSC) inspection history

No. of Inspections in Past three years:

14

No. of Deficiencies in Past three years:

21

No. of Detentions in Past three years:

0

Is the vessel flag targeted by Port State Authorities?

☒ No

Is an effective system of security access control, conforming to ISPS standards, in place upon boarding the vessel?

☒ Yes

Type of access control

gangway watch, visitors log, ID check, visitor's badge, escort

Do the Master and Chief Engineer have an effective hand over procedures?

☒ Yes

Are random or specific drug and alcohol testing carried out?

☒ Yes

Tests Carried out by

Onboard by Master

Were the Master and crew prepared for the Inspection?

☒ Yes

What level of cooperation was provided by the crew and Master?

Good

Were documents provided as requested?

Majority of documents provided

What was the overall impression of the general management of the vessel?

Well managed

VESSEL CAPABILITIES AND CARGO SYSTEMS - GENERAL CARGO

Vessel Capabilities and Cargo Systems - General Cargo Condition

Cargo hold	Capacity (m³)	Capacity in holds (TEU)	Steel Coil capacity by: Total weight (mt)	Capacity on deck (TEU)
Cargo Hold No.1	4,822.8		2,225	
Cargo Hold No.2	10,624.4		6,325	
Cargo Hold No.3	10,627.6		6,325	
Cargo Hold No.4	10,893.4		6,325	
Cargo Hold No.5	10,215.1		4,225	
Total	47,183.3	0	25,425	0

How many cargo holds does the vessel have?

5

Were the cargo holds able to be entered and inspected?

☒ Yes

Which holds were entered

all 5 holds entered as far as practical due to on-going cargo operations

Were recent vessel cargo hold inspection photographs provided?

☐ No

Were cargo holds structural members found to be free from damage (e.g. side plating, tank top and framing)?

☒ Yes

Were the cargo hold fittings such as ladders, hand rails and pipe guards etc. found to be free from damage?

☒ Yes

What was the level of cargo hold coating breakdown and corrosion?

Minor

Coating breakdown and corrosion was mainly located in the following areas:

to corrugated bulkheads

The amount of surface area coating breakdown and corrosion was approximately:

2%

Type of coating breakdown and corrosion:

☒ Localised☒ Spot

If the vessel is geared, does the vessel have heavy lift Capabilities?

☒ No

What was the last cargo carried?

aluminum ingots

What is the next intended cargo to be carried?

not yet known

Were cargo hold bilges dry, clean and clear of debris or cargo?

☒ Yes

Were the cargo holds free from signs of water ingress?

☒ Yes

Were the cargo holds free from signs of previous and/or current internal leaks (e.g. from manholes or adjacent tanks etc)?

☒ Yes

What is the method of cargo hold ventilation?

Natural

Hatch Covers Condition

What type of hatch covers are fitted?

Hydraulic folding type

Were the hatch covers found to be correctly aligned?

☒ Yes

Were the hatch cover found to be free from structural damage?

☒ Yes

What level of coating breakdown and corrosion was seen on the hatch covers?

Minor

Coating breakdown and corrosion was mainly located in the following areas:

to top sides and lower side edges with signs of on-going cosmetic maintenance noted

The amount of surface area coating breakdown and corrosion was approximately:

5%

Type of coating breakdown and corrosion:

☒ Scattered

☒ Spot

Were the hatch cover operating systems found to be fully operational?

☒ Yes

What was the condition of the hatch cover operating system, free from corrosion, leakage etc.?

Fair

Please provide further details

areas of corrosion noted to wheels, hinges, hydraulic cylinders as well as a leak noted from the port forward cylinder for hatch number 4

What was the condition of the hatch cover rubber seals/gaskets and retaining channels?

Good

What was the condition of hatch cover securing arrangements?

Good

What was the condition of hatch cover hold-open arrangements?

Good

What was the condition of the hatch cover landing pads?

Good

Hatch Coamings Condition

Were the hatch coamings found to be free from structural damage?

☒ Yes

What was the level of hatch coaming coating breakdown and corrosion?	Minor
Coating breakdown and corrosion was mainly located in the following areas:	in difficult to maintain areas, underside of stiffeners, and on edges of brackets
The amount of surface area coating breakdown and corrosion was approximately:	3%

Type of coating breakdown and corrosion:

☒ Localised☒ Surface

Were the compression bars/strips seen to be in good condition?

☒ Yes

Were the hatch coaming drain channels seen to be free from corrosion, scaling or debris?

☒ Yes

Were hatch coaming non-return valves found to be clear and fully operational?

☒ Yes

Documentation and Additional Features

Does the vessel have a Document of Compliance (DOC) for the carriage of dangerous goods?

☒ Yes

Does the vessel have a Certificate of Authority to carry grain?

☒ Yes

Was there an approved Cargo Loading Manual on board?

☒ Yes

Is the vessel certified to carry heavy cargoes?

☐ No

Was there an approved stability booklet on board?

☒ Yes

Did the vessel use a Class-approved computer based loading/stability software?

☒ Yes

Name of software:

multiload

Were previous and current stability calculations seen to be carried out?

☒ Yes

Is the vessel fitted with movable bulkheads and tween decks?

☐ No

What was the condition of the tween decks and movable bulkheads?

Fair

Please provide further details

vessel does not have tween decks and movable bulkheads

What was the condition of the vessels lashing equipment?

Fair

Please provide further details

vessel does not have lashing equipment set on board.

Was there an up to date lashing inventory?

☒ No

vessel does not have lashing equipment set on board

What was the condition of fixed cargo securing fittings, such as container sockets, pad-eyes, D-rings and fixed stacking cones, etc.?

Good

Reefer Containers

Is the vessel equipped to carry Reefer containers?

☒ No

Reefer Capacity

Total

0

CARGO LIFTING APPLIANCES

Cargo Lifting Appliances Condition

Crane	Safe Working Load (SWL) (t)	Reach (m)	Date of last wire change
1	30	26	28-Jan-21
2	30	26	06-Dec-21
3	30	26	22-Feb-21
4	30	26	04-Jan-20
How many Cargo Lifting Appliances does the vessel have?	4		
What type of cargo lifting appliances are fitted?	electro-hydraulic (mitsubishi) jib cranes.		
Were the cargo lifting appliances seen in operation?	<input checked="" type="checkbox"/> No		
Were all cargo lifting appliances fully operational?	<input checked="" type="checkbox"/> Yes		
Were the cargo lifting appliances found to be free from structural damage?	<input checked="" type="checkbox"/> Yes		
What level of coating breakdown and corrosion was seen on the cargo lifting appliances?	Minor		
Coating breakdown and corrosion was mainly located in the following areas:	on jibs, inspection platforms, around slewing bearings, around operator cabins, and to pedestal		
The amount of surface area coating breakdown and corrosion was approximately:	10%		

Type of coating breakdown and corrosion:

☒ Localised☒ Surface☒ Spot

In what condition were the wires for the cargo lifting appliances?

Good

In what condition were the cargo lifting appliances motors and hydraulic systems?

Good

In what condition were the cargo lifting appliances slewing bearings?

Fair

*Please provide further details**some corrosion around bearings and on bolts (external), more so to crane number 1*

Was slewing bearing wear monitored or rocking tests conducted and recorded?

☒ No*no data provided for review*

Were all safety features and equipment (e.g. limit switches) fitted on the cargo lifting appliances fully operational?

☒ Yes

In what condition were the cargo lifting appliances control and operating positions, including their operator cabs if fitted?

Good

Were cargo lifting appliances regularly examined by appropriately qualified shore side technician?

☒ Yes

Were cargo lifting appliances angle indicators free to move?

☒ Yes

Was the Safe Working Load (SWL) clearly marked on the cargo lifting appliances?

☒ Yes

What condition were the cargo lifting appliances components such as sheaves, blocks and cylinders in?

Good

Were cargo lifting appliances maintenance records accurate and up to date?

☒ Yes